



HOW TO CHECK YOUR INSPECTION RESULT



Once you have logged in click on **My Account**.



Click on **Inspections**.

Profile - Inspections - ViewPoint Cloud

dauidsoncountync.viewpointcloud.com/dashboard/inspections

County of Davidson, NC My Account Search John

Back Home

- Dashboard
- Messages
- Profile
- Your Records
- Applications
- Projects
- Permits & Docs
- Payments
- Inspections

Inspections

Inspection	Record	Location	Status
Electrical Rough Inspection	Electrical Permit E-22-776	912 Greensboro Street Lexington, NC 27292	Active
Gas Line Rough Inspection	Mechanical Permit	Lexington, NC 27292	Active
Final Building	HIST_Building Permit	Lexington, NC 27295	Complete
Stone Prep	HIST_Building Permit	Lexington, NC 27295	Complete

Click on the **Permit/Address** of the permit you wish to check the inspection on.

Record E-22-776 - ViewPoint Cloud

dauidsoncountync.viewpointcloud.com/track/222684/step/513475

County of Davidson, NC My Account Search John

Electrical Permit
E-22-776

Your Submission
Attachments
Guests (0)

- Intake Review/Fee Assessment
- Permit Fees
- Electrical Permit
- Electrical Rough Inspection**
 - Electrical Final Inspection
 - Certificate of Compliance Issuance

Electrical Rough Inspection

In progress. This inspection is in progress.
PLEASE PROVIDE ALL LOCK BOX CODES, GATE CODES, AND ACCESS CODES WITH EACH INSPECTION REQUEST

Request an Inspection

When you're ready for an inspection, you can request one by clicking the button below.

[Request Inspection...](#)

Inspection Checklist

Electrical Rough
Fail

Inspection History

Date	Inspector
Nov 7, 2022	Inspector's Name

Click in the rectangle area where it shows the **Date** of the inspection and the **Inspectors Name**.

The screenshot shows a web browser window with the address bar displaying "davidsoncountync.viewpointcloud.com/inspection-report/18291". The page header includes "County of Davidson, NC", "My Account", "Search", and a user profile for "John". A link for "Back to overview" is visible. The main content area is titled "Inspection Report" and contains the following details:

- Inspection:** Electrical Rough Inspection
- Inspector:** Inspectors Name
- Inspection Date:** Nov 7, 2022 at 12:00am
- Record:** Electrical Permit #E-22-776
- Location:** 912 Greensboro Street, Lexington, NC 27292
- Applicant:** John Doe

Below the details, there is a section titled "Electrical Rough" with a yellow highlight. Underneath, it shows "Overall Result: Fail" in a red box, followed by "Overall Remarks:" and a text box containing the placeholder text "THIS IS WHERE THE INSPECTION RESULTS FROM THE INSPECTION WILL BE".

Here is where you will see the **Results** from your inspector on whether it has **passed or failed**.